Approved For Release 2009/98/21 : CIA-RDP33-02415A000200270019-9



MEADQUARTERS 4070TH SUPPORT WING (SAC) March Air Force Base California

					25X1A2g	26 October 1956	1	
	SUBJECT:	Report on 0 18 Septembe	Werseas V: er to 17 0	isit (Prejec tober 1956	It)		
	TO:	Commander 4070th Supp March Air F California		SAC)				
25X1A9a	I. Lieutenant Colonel A. M. Lien, Chief of Supply, 4070th Support Wing, accempanied of Project Headquarters and Management the Project Depot Supply Officer, on an overseas visit to the two 25X1A9a Weather Reconnaissance Squadron locations to investigate reported support difficulties, and, if required, to coordinate corrective actions with Headquarters USAFE, USAF, and Project Headquarters. Report follows in a general chronological order:							
25X1A6a	visiting warded by at statement on, mean reported the new because future Detachment would also	2. On arrival at Project Headquarters on 19 September 1956, the visiting group was briefed on the several messages that had been forwarded by the Commander, Detachment "B," regarding the lack of support at Areas of reported non-support included transportation, messing, and expendable type supplies. Detachment "A" had not reported any major difficulties; however, the unit would be visited and the new base currently under preparation to receive this unit in the near future would be surveyed to determine its capability to support the Detachment's mission. Further, the ZI depot support and pipeline status would also be checked to determine the effectiveness of that operation. The group departed Washington on 19 September 1956.						
25X1A6a 25X1A6a	noon of 20	4070th Supp	1956. Det port Wing was stated	achment "A" Liaison Off as excelle	icer, were cont, however	on the after- lves and Major entacted, and come delay in the		
25X1A6a	reported. of Materia discuss th	On 21 Septe 1, USAFE, and e purpose of	ember, the nd Lt Col f the visi	group met : Marthens, P. t. Brigadi	with Brig Ger roject Office er General Li	Light, Director or, USAFE, to ght indicated wmended specific		
25X1A6a 25X1A6a	hand data Marthens v ation at Brigadier	reserved uni regarding these designate General Light at the base	til the gr ne reporte ed to acco nt indicat e be comple	oup visited d difficult: mpany the vi to support ! ed that he a sted prior !	the base to ies. Lieuter isitors to me Detachment "/ desired that to moving the	obtain first cant Colonel The prepar- "was discussed. all operational unit from	•	
25X1A6a App i	This docume		_		Trans.	100 1956 was		

Approved For Release 2000/08/21 : CIA-RDP33-02415A000200270019-9

contingent on completion of the facilities. It was agreed that all concerned would meet with Headquarters USAFE representatives on completion of the survey of both to arrive at 25X1A6a actions required to resolve any support deficiencies noted during the survey. 25X1A6a

25X1A9a

4. The group departed for on 22 September, arriving there on the morning of 24 September 1956. On arrival, Detachment "B" Gommander, established a conference with the Adams Base Commander and his Material Staff. Findings at were as follows: 25X1A6a

a. The maintenance and operational facilities were completed and considered excellent. Unsatisfactory blower motors in the heating system was the only reported deficiency as pertained to the facilities. Project Headquarters accepted the responsibility for obtaining replacement motors.

- b. The base construction program to include an officers club. service club, and theater was progressing satisfactorily and should be completed by January 1957. These facilities are urgent requirements as recreational facilities are now practically non-existent. 25X1A6a
- c. The reported unsatisfactory field mess at was considered a valid complaint. The quality of the food was below average and sanitation practices were sub-standard as evidenced by the considerable number of dysentery dases reported by Detachment "B's" medical officer. The mess condition was the most severely criticized deficiency 25X1A6a by the majority of Detachment "B's" personnel. The commander acknowledged that the mass required improvement and attributed the situation to a personnel problem. The Food Service Officer and senior Non-Commissioned Officer were being relieved and replacements were en route from other bases. The USAFE representative took action to assign a USAFE mess assistance team of one officer and three food service technicians to to a temperary period. This team has an excellent reputation for improving messing conditions throughout the command. Other corrective actions will include procurement of dishes, glasses, silverware, water coolers, and other items to improve the appearance 25X1A6a and capability of the mess. Major Jones, 4070th Liaison Officer, will review the mess condition with mess capability at the when con-25X1A6

25X1A6a

25X1A9a

d. The ground transportation support was inadequate at the time of the visit due to the delayed arrival of the bus ellocated to

sidered in relation to the quality of the food to which the Detachments were accustomed in the ZI, will be a difficult problem area to overcome, and at its best will probably be barely acceptable to the type of per-

Approved For Release 2000/08/21 : CIA-RDP33-024

somel involved in this project.

Approved For Release 2000/08/21 : CIA-RDP33-02415A000200270019-9

the Detachment. Later information indicates that the bus arrived 25X1A6a **≜**\$ on 29 September 1956. Other vehicles, such as jeeps, weapons, carriers, and pick-ups were not in the best mechanical condition and occasional breakdowns were being encountered. On 26 September, 52 out of 156 vehicles were out of commission and the lack of parts was responsible for h7 of the grounded units. USAFE authorized the base to use spares to repair vehicles and a 25X1A2q civilian contract was being formulated to have a reputable repair authorised to perform maintenance and repair of Air 25X1A6a Force equipment. Further the Detachment "B" Commander utilized Project funds to purchase a quantity of motor scooters for key persommel of his organization. The above combined actions should improve the transportation support to an acceptable degree. e. From an eperational aspect, the supply support could 25X1A6a the most serious problem area. When Detachment "B" arrived at certain required expendables were not on hand. Examples were hydraulic fluid, welding gases, nitrogen, office supplies. and common hardware. The T-33 Table II spares that were shipped to by a C-12h aircraft on 8 August 1956 remained in outside storage. The base had not inventoried or posted subject spares to base supply records. Action to warehouse and record subject spares was started during the visit. Lieutenant Poerschke, Project Project Officer at Noussuer, 25X1A2q during this visit and indicated that all Project 1500 5X1A2q 25X1A6a 25X1A2q requisitions would receive priority handling by his office. He emphasised however, that the depot could not provide items coded Local Purchase. Based on an AMC directive, all Local Purchase requirements not procurable in the immediate area of the base must be requisitioned from the Area Procurement Office located at 25X1A6a this office has not been assigned this responsibility until this fiscal year, the support rendered to date has not been too satisfactory. Therefore, it was decided to follow a "fill or kill" requisitioning 25X1A6a procedure with and that priority requirements for Local Purchase 25X1A6a items not available at second be forwarded direct to the USAFE Project Office for supply action. If not available from WAFE resources, the requirements will be forwarded to the Project Supply Depot at California. Pipeline time and communication difficulties also con-25X1A6a tribute to the difficult supply support in this area and close monitorship and follow-up of all requisitions by the Detachment Supply Officer will be required. It is appropriate to note that our letter of requirements forwarded to Headquarters USAFE on 15 June 1956, and subsequently forwarded to the had not been implemented, and that supply action to obtain the various expendables outlined in this letter was not initiated 25X1A6a prior to this survey. 25X1A6a

25X1A6a

f. A C-54 and two T-33 aircraft were on hand at Ground maintenance personnel for the G-54 had been assigned to the base but aircraft spares were not on hand. Periodic inspections will be accomplished at the periodic inspections will be accomplished at the periodic inspections. This unit, however, possesses only limited G-54 aircraft spares

AH 1 3 5 4 - 6
Approved For Release 2000/08/21 : CIA-RDP33-D2415-000230270019-8

Approved For Release 2000/08/21 : CIA-RDP33-02415A000200270019-9

and was unable to clear several major defects on the aircraft the week prior to the visit. T-33 periodic inspections will be accomplished at Wheelus Air Force Base. A decision was reached to place an en route Flyaway Kit aboard the C-54 aircraft to insure routine maintenance can be supported regardless of the aircraft's location. Subject spares will be assembled at the subject spares will be assembled at 25X1A6a shipped to both Detachments. Parachute riggers had not been assigned at the time of the visit; however, on return to Headquarters USAFE it was learned that a rigger had been dispatched to and that the 25X1A6a Turkish Air Force facility would be utilized to accomplish parachute repacking. 25X1A6a g. The receiving section of Base Supply at was experiencing difficulty in identifying Detachment "B" property as all supplies, including construction items, were being marked for 25X1A2q In several instances sireraft parts and other supplies needed by the Detachment were picked up by base personnel and moved to their operating location. It is believed that arrangements made with the base to more closely monitor receipts of supplies and the distinctive marking of containers destined for the Detachment will eliminate this problem. Pipeline time to date on supplies flowing through Charleston, S.C., averaged 1h to 18 days from the date shipped 25X1A6a from Based on previous experience it is not believed that this pipeline time can be reduced appreciably. h. The machine shop which was procured by the aircraft contractor had been installed, but was not fully operable due to a power problem. Starter relays for most of the machinery were not adaptable to the 220V power supply. Different relays would be required before this situation could be remedied. The Project Depot Supply Officer agreed to obtain the necessary relays from the aircraft contractor and to sirmail them to Detachment "B." i. All contractor representatives were contacted to review any problem area that could be resolved by the combined efforts of the visiting group. Certain equipment and Flyaway Kit change recommendations were accepted for inclusion in the next printing of the authorisation documents. A major change involved the addition of a photo-lab capability within the unit to process test film strips and other requirements such as pictures to support unsatisfactory reports. Prior to 25X1A9a departure from a combined meeting was held with and col Thomas, the Base Commander, to review findings and actions required. 25X1A6a The expendable requirement letter of 15 June 1956 and the Overseas Logistical Support Plan 400-1 were reviewed with all concerned and action was initiated by the Base Materiel Staff to comply with all requirements stated in the two documents. It is noted that the present 25X1A6a Materiel Staff at was only recently assigned and that some of the support problems can be attributed to the complete change-over of key

AH 1354-6 Approved For Release 2000/08/21 : CIA-RDP33-02415A000200270010-0 6

25X1A6a *t

personnel at the time that the support should have been prepositioned

Approved For Release 2000/08/21: CIA-RDP33-02415A000200270019-9

25X1A6a

5. The survey party returned to Headquarters USAFE on 27 Sep 56. was visited to review construction progress and to determine the support capability of that station. Findings were as follows:

a. The construction progress included the renovation of a 2h0' x lh0' hangar, erection of three h0' x 100' Butler type buildings for warehousing, quarters for approximately 120 personnel, and a 40' x 100' Butler building for use as an efficers club. On 12 Oct 56. the hangar to include office space for the entire operation, photolab, communications, and the pre-breathing facility was completed except for electrical power. Two 190 KVA Generators were on the base and were scheduled for installation and connection prior to 15 Oct 56. The warehouse buildings were completed. The ten structures to be used for living quarters were completed except for tiling and painting the bathrooms. This work was scheduled for completion by 25 Oct 56. New furniture was being installed. The officers club was erected; however, the interior work was delayed pending availability of funds. Subject funds were made available by Headquarters USAFE on 13 Oct 56. The lack of this facility would not delay the movement. 25X1A6a

25X1A6a

25X1A6a

25X1A6a

25X1A6a 25X1A6a

b. As there is no supply account established at the 7030th Support Group at Ramstein Air Force Base will provide all common type supplies. Romstein is which can be an unsatisfactory feature. Headquarters USAFE directed Headquarters Twelfth Air Force to investigate the possibility of establishing a supply account at the earliest possible date.

6. On 4 October 1956, a conference was held at Headquarters USAFE with representatives of that headquarters, AMFEA, 7030th Support Group, and Detachment "A" to resolve certain support procedures that would be implemented when Detachment "A" was in place at Other problems as pertained to Detachment "B" at were discussed with AMPEA representatives. Inclosure 1 reflects the official minutes of this meeting. This conference was instrumental in establishing supply requirements through the normal theater supply channels and should improve the future support rendered both Detachments.

25X1A6a

7. Lieutenent Colonel Lien remained at Headquarters USAFE and Detachment "A" until 14 October 1956 to memiter Detachment "A's" activities and to meet with Brig Can Light who was temperarily away from the headquarters. On his return, Brig Gen Light was briefed on 25X1A6a the survey of send and send and was advised that actions now in progress appeared satisfactory. Brigadier General Light expressed concern regarding certain reports being provided Headquarters USAF regarding the unsatisfactory conditions at that had not been brought to the attention of Headquarters USAFE, and requested that,

25X1A6a 5456

Approved For Release 2000/08/21 : CIA-RDP33-02415A000200270019-9

in the future, his headquarters be made sware of problems and afforded an opportunity to take appropriate action to resolve any difficulties prior to Headquarters USAF being advised of the deficiencies. This information was passed on to Project Headquarters and the Project Office, Headquarters USAF, on return to Washington, D.C.

5. The Strategic Air Command role in monitoring the overseas support of the Detachments was discussed with Brig Gen Light and the Project Office, Headquarters USAF. General Light indicated that SAC Liaison support should not be required if all levels of command within the theater properly accomplished all functions as outlined in the Overseas Logistical Support Plan. He also stated, however, that there was no objection to Strategic Air Command representation to assist in the support monitorship, but that the representatives should be attached to Headquarters USAFE for control and appropriate direction. Disgussions at the Project Office. Headquarters USAF, considered a letter from Headquarters SAC to Headquarters USAF, requesting relief from the overseas monitorship responsibility. The Project Office indicated concurrence with the request and will recommend to the Air Staff that Strategic Air Command be relieved of the everseas support responsibility, and that the various letters of requirements and logistical plans, prepared by the 1070th Support Wing, be forwarded to the overseas commands concerned by the Project Office, Headquarters USAF. An official reply to General Terrill's letter can be expected in the near future. It is emphasized, however, that until SAC is completely relieved of the overseas support responsibility, there is a tendency by certain USAFE representatives to indicate that more extensive monitorship by SAC Liaison personnel could prevent many of the difficulties encountered to date. Therefore, if SAC is not relieved of the overseas support function in the immediate future, recommend that the assignment of additional personnel to everseas Liaison duty be considered as soon as possible. It is appropriate to note that Major Donald A. Jones was selected as the LO70th Support Wing Liaison Officer at the time that Detachment "A" was located at that the majority of his efforts since July 1956 has been concerned with the deployment of the unit to and monitoring the support of Detachment "A" at In addition, Najor Jones has been arranging for shipment to meet of property originally purchased at manufactured for Detachment "A," and has also been responsible for returning equipment to manufacture that was temporarily borrowed to support the operation in the control of equipment was scheduled for completion by 15 November 1956.

25X1A6a 25X1A6a 25X1A6a 25X1A6a 25X1A6a 25X1A6a 25X1A6a

9. Lieutenant Colonel Lien returned to March Air Force Base on 17 October 1956.

1 Incl
Memo for the Record
(Eq USAFE) 5 Oct 56

ARTHUR M. LIE O O O O S

Lt Colonel, USAF

Chief of Sapply

Approved For Release 2000/08/21 : CIA-RDP33-024154000200270019-9